

## YARD TRUCK COSMETIC INSPECTION FORM

UNIT #:	4602
INSPECTOR:	Joshua Serva
DATE:	7/8/22

PASSENGER-SIDE CAB CAB-FRONT CAB EXTERIOR CONDITION & APPEARANCE 9 Inspect Exhaust Stack & Heat Shield 00 O 7 Inspect Window Glass & Seals 5 Inspect Sheet Metal Body & Hood Panels 4 Inspect Windshield Glass & Gasket 1 Inspect Sheet Metal Body Panels & Seals 3 Inspect Bumper 2 Inspect Grill Panel(s) Inspect Side Mirror & Hardware Inspect Hood Hardware & Operation SATISFACTORY NEEDS REPAIR NOTES Dumper Bed lest NO Stack off-road 84 Capacity

DRIVER-SIDE		
10 Inspect Sheet Metal Body & Door Panels		Door Hos have Mondold Bottom
		RARS
11 Inspect Door Hardware & Operation	<	
12 Inspect Window Glass & Seals	5	
13 Inspect Side Mirror & Hardware	<	
14 Inspect Grab Handle, Step Ladder & Body Accessories	~	
CAB-REAR		
15 Inspect Sheet Metal Body & Door Panels		
		Poor & France But.
16 Inspect Door Hardware & Operation	ul .	
		Service Servic
17 Inspect Window Glass & Seals	,	
18 Inspect Grab Handle & Rear Body Accessories	<	
CAB-TOP		
19 Inspect Sheet Metal Body Panels		

## FRAME/CHASSIS

FRAME/CHASSIS CONDITION & APPEARANCE 30 Inspect All Exterior Light Function & Appearance 29 Inspect All Other Frame Mounted Tanks & Components 28 Inspect Battery Box 27 Inspect Fuel Tank(s) 26 Inspect Mudflaps & Brackets 25 Inspect Fenders & Brackets 24 Inspect Axles & Differential Appearance 23 Inspect Fifth Wheel Plate & Boom Arms 20 Inspect All Wheels & Hubs 22 Inspect Main Frame Rails 21 Inspect Grates SATISFACTORY NEEDS REPAIR NOTES P M1851mg W 1851 W Hagdradic Fluid level glass weeds Kustes 1319 Grate needs Repair Point work & Some lights conted

31 Inspect Seat & Seat Frame	-	
32 Inspect Roof Liner & Roof Components	<b>V</b>	
33 Inspect Interior Body Metal Surfaces	<u> </u>	
34 Inspect Interior Door Surfaces	2	
35 Inspect Floor & Floor Liner	4	
		The State
Inspect Front Dash Panel		
	m/29,1W	My Same Gauges
38 Inspect Side Dash Panel		
		Missing Peice
39 Inspect All Gauges & Displays	<	Ć.
40 Inspect All Instrument Controls		
	NAMENDO DE CONTRACTOR DE LA RECONSTRUCTOR DE CONTRACTOR DE	
41 Inspect A/C Vents		N.
		But sex
42 Inspect Under-Dash Area	< - 1	
43 Inspect Window Components & Seals		