

DIAGNOSTIC REPORT

VIN: 1T9NSHA86KR825066

Model Year: 2019

Manufacturer:

COMPONENT	FAULT CODES	5 TOTAL / 0 ACTIVE / 5 INACTIVE
-----------	-------------	---------------------------------

ENGINE #1 - J1939

ACTIVE FAULT CODES (0)

Vehicle Make: Cummins

None

ECM Serial Number: 74431061

ECM Model: 6B u14D067

VIN: 1T9NSHA8QKR825066

INACTIVE FAULT CODES (5)

Fault Description: ECL SPN 111

FMI Description: Data Valid but below Normal Operating Range - FMI: 18

Moderately Severe Level

Count: 31

Fault Description: ECL SPN 111

FMI Description: Data Valid but below Normal Operational Range - FMI: 1

Most Severe Level

Count: 30

Fault Description: Transmission Output Shaft Speed SPN 191

FMI Description: Abnormal Update Rate FMI: 9

Count: 2

Fault Description: Vehicle Speed SPN 84

FMI Description: Abnormal Update Rate FMI: 9

Count: 2

Fault Description: Catalyst Tank Level SPN 1761

FMI Description: Data Valid but below Normal Operating Range - FMI: 17

Least Severe Level

Count: 2

TRANSMISSION #1 - J1939

ACTIVE FAULT CODES (0)

Vehicle Make: N/A

None

ECM Serial Number: N/A

ECM Model: N/A

VIN: N/A

INACTIVE FAULT CODES (0)

None

UNKNOWN/RESERVED (SA

ACTIVE FAULT CODES (0)

ECM Serial Number:

None

ECM Model:

INACTIVE FAULT CODES (0)

None

INSTRUMENT CLUSTER #1 -

ACTIVE FAULT CODES (0)

ECM Serial Number:

None

ECM Model:

INACTIVE FAULT CODES (0)

DIAGNOSTIC REPORT

VIN: 1T9NSHA86KR825066

Model Year: 2019

Manufacturer:

COMPONENT FAULT CODES 5 TOTAL / 0 ACTIVE / 5 INACTIVE

None

SHIFT CONSOLE - PRIMARY - ACTIVE FAULT CODES (0)

ECM Serial Number: None

ECM Model:

INACTIVE FAULT CODES (0)

None

PARAMETERS

ENGINE #1 - J1939

Rated Horsepower	158 BHP	Engine Rated RPM	Not Available
MIL Status	Off	Fuel Level	N/A
Battery Voltage	11.05 V	Ignition Voltage	Not Available
Engine RPM	0 RPM	Vehicle Speed	0 mph
Throttle Position	0 %	Brake Switch	Released
Clutch Switch	Released	Engine Operating State	Engine Stopped
Engine Intake Air Temperature	Not Available	Engine Intake Air Pressure	Not Available
Barometric Pressure	Not Available	Coolant Level	100 %
Coolant Temperature	59.0 °F	Oil Level	Not Available
Oil Temperature	Not Available	Oil Pressure	0.0 psi
DPF Status	Regen not Needed	Regen Status	N/A
DPF Active Regen Inhibited Status	Inhibited	DPF Active Regen Inhibited Due to Inhibit Switch	Not Inhibited
DPF Regen Inhibit Switch	N/A	DPF Regen Force Switch	Inactive
Exhaust Temperature 1	N/A	Exhaust Temperature 2	N/A
Exhaust Temperature 3	N/A	DPF Intake Temperature	N/A
DPF Outlet Temperature	N/A	DPF Differential Pressure	N/A

TRANSMISSION #1 - J1939

Battery Voltage	N/A	Ignition Voltage	N/A
Input Shaft Speed	0 RPM	Output Shaft Speed	0 RPM
Oil Level	Not Available	Oil Life Remaining	N/A
Oil Temperature	60.0 °F	Service Indicator	N/A
Range Selected	N/A	Range Attained	N/A

DIAGNOSTIC REPORT

VIN: 1T9NSHA86KR825066

Model Year: 2019

Manufacturer:

LIFE DATA

ENGINE #1 - J1939

Distance	30201.03 mi	Hours	14708.40 hr
Fuel Used	19548.2 gal	Average Fuel Economy	N/A
Engine Idle Hours	9982.70 hr	Engine Idle Fuel Used	10134.2 gal
PTO Hours	0.00 hr	PTO Fuel Used	0.0 gal
DPF Number of Inhibited Active Regen	Not Available	DPF Number of Manual Active Regen	Not Available
DPF Fuel Used	70.3 gal		

TRIP DATA

ENGINE #1 - J1939

Distance	30218.12 mi	Fuel Used	19475.7 gal
Average Fuel Rate	1.32 gal/hr	Idle Time	N/A
Vehicle Idle Fuel Used	10134.2 gal	Cruise	N/A
Cruise Fuel Used	0.0 gal	DPF Active Regen Time	N/A
DPF Number of Active Regens	N/A	DPF Used	N/A
Vehicle Speed Limit	20 mph	Cruise Control Speed Limit	Not Available